

**Cottonwood Creek (HSA 4.51)** at Cottonwood Creek Park downstream (d/s) of Coast Highway (Hwy) crossing (xing). 2005 Thomas Brothers page 1147 B6. Streamflow ~ 0.75 cfs. Riparian restoration in progress. Riparian habitat consists of willow, cottonwood, cattails, California evening primrose, watercress and other vegetation.



a. Cottonwood Creek, at Cottonwood Creek Park downstream (d/s) of Coast Highway crossing. Willow riparian habitat. July 12, 2005 0905hrs.



b. Cottonwood Creek, at Cottonwood Creek Park d/s of Coast Hwy xing. Willow riparian and cattails. July 12, 2005 0903hrs.



c. Cottonwood Creek, at Cottonwood Creek Park d/s of Coast Hwy crossing. Willow riparian habitat. July 12, 2005 0905hrs.



d. Cottonwood Creek, at Cottonwood Creek Park d/s of Coast Hwy crossing. Willow riparian, watercress. July 12, 2005 0911hrs.



e. Cottonwood Creek, at Cottonwood Creek Park d/s of Melrose Avenue crossing. Flow ~  $\frac{3}{4}$  cfs on July 12, 2005 at 0913hrs.

f. Cottonwood Creek, d/s of Melrose Avenue xing looking towards Moonlight Beach.

Watercress covers creek.

July 12, 2005  
0912hrs.

